



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 07/09/2014

Reviewed

PRB

Mine Name: Morgan Facility	Permit Number: M/029/0008	Mine Status: Active
Operator Name: Geneva Rock Products, Inc.	Inspection Date: 07/31/2013	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: 12:30 PM	Bond Amount: \$450,000
Attendee(s): none	Weather: Sunny, Dry	Bond Escalation: 04/04/2015
Inspection Purpose: Routine annual inspection		Prior Inspection: 11/30/2010

Conclusions and Recommendations

The Operator needs to stockpile topsoil, implement storm water runoff sediment ponds, both on a regular basis. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Operator is current with permit fees. Bond escalation is due as shown above .	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> Project is gated, but highwall is significant, original highwall was oversteepened and will need to be fixed prior to closure.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No erosional problems noted, nor was there any evidence of any erosional problems.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> Fuel storage needs to be updated	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were maintained and in good condition - see attached photos.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> Possible soil stockpiles at the base of the hill.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> No site revegetation has been started.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC: Brent Sumsion - Geneva Rock Product, Inc.

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M029-Morgan/M0290008-MorganFacility/inspections/INSP-07312013.pdf



Entrance



Gate



Road maintained with water



Road with asphalt pavement



Fuel Storage



Laydown yard



Product stockpiles - note topsoil stockpile in background



Product stockpiles




Old south highwall -



Old south highwall



New north highwall



New north highwall